

IMPORTANT SAFETY NOTICE

ROCK SHOX® Lyrik™/Yari™ front suspension forks

ROCK SHOX Lyrik fork:



ROCK SHOX Yari fork:



Casting code on the inside of arch web:



Example of casting code 18 O

Above are views of both full forks and a view of the inside webbing of the arch containing a casting code.

SRAM, LLC has determined that the lower leg assembly of the affected forks can fatigue prematurely and break, which may cause the rider to lose control and fall. UPC codes do not appear on the forks. However, the serial numbers appear on the forks. ROCK SHOX Lyrik and ROCK SHOX Yari forks for 29 inch Boost wheels within the serial number range of 02T95514009 to 08T96214665 and having a fork lower leg with a casting code of “18” and “O” or “19” and “A” are affected by the recall. The serial number can be found on the rear of the fork crown. The casting code can be seen inside the webbing of the arch as shown above.

Consumers with bicycles equipped with a potentially affected fork should stop riding immediately and return their fork to SRAM or their local bicycle dealer for verification and to obtain a free replacement product.

For more information, please go to our website: www.SRAM.com

Retailer: Please post until _____